



Product Change Notice (PCN)

Date: 6/20/2019

PCN Number: PCN-0450480R-01

To Our Customers:

We appreciate your use of our products. Our commitment in maintaining and improving processes is demonstrated by plans to enhance our product quality, reliability, and manufacturability. The purpose of this notice is to inform you of a product change.

Product(s) Affected: *MJ-3507*

Reason(s) for Change: *The existing mold of pin 3 for MJ-3507 is unable to maintain efficient production. To ensure the quality and lead-time of production, a re-development of the mold has been processed. The new mold will optimize the design by increasing the chamfer of pin 3 inside the product. The electrical structure and function will remain the same. (The comparison photos are available below).*

Description of Change: *Photos of changes included below.*

Affected Date Code: *12/31/2019*

Product Availability: *Currently available*

Additional Information: *No change to form, fit, or function*

PCN Approval:

Operations/Quality







A handwritten signature in black ink, appearing to read "Sam Wood", is written over a horizontal line.

Product Management

A handwritten signature in black ink, appearing to be initials, is written over a horizontal line.

F-723-001

Revision: A

	New version	Current version
Back	 <p>pin 3 added chamfer.</p>	 <p>pin 3 without chamfer.</p>
	 <p>pin 3 is continuous piece, with cutting mark.</p>	 <p>pin 3 is separate piece, without cutting mark.</p>
	 <p>pin 3 added chamfer.</p>	 <p>pin 3 without chamfer.</p>